




ARRIVAL ROUTE DESCRIPTION

HARPO TRANSITION (HARPO.CAMPS4): From over HARPO on LNY R-095 to CAMPS.
Thence

LANAI TRANSITION (LNY.CAMPS4): From over LNY VORTAC on LNY R-095 to CAMPS.
Thence

. . . . cross CAMPS at or above 3000, then on I-OGG localizer course. Expect
ILS Y or LOC Y RWY 2 approach.