


VOR RWY 36
MERIDEN MARKHAM MUNI (MMK)

MISSED APPROACH: Climbing right turn to 2700 on HFD VOR/DME R-251 to MIDDL INT/HFD 10.6 DME and hold, continue climb-in-hold to 2700.

UNICOM
123.05 (CTAF) **L**

2700

HFD R-251

MIDL INT

JUMGO INT
MAD 10.5

ACALA INT
MAD 8.5

One Minute Holding Pattern

165°

2100

345°

1800

345°

1060

3.50°

TCH 38

2.5 NM

2 NM

CATEGORY	A	B	C	D
S-36	1060-1¼ 961 (1000-1¼)	1060-1½ 961 (1000-1½)		NA
CIRCLING	1060-1¼ 957 (1000-1¼)	1060-1½ 957 (1000-1½)		NA
JUMGO FIX MINIMUMS (DUAL VOR RECEIVERS OR DME REQUIRED)				
S-36	880-1 781 (800-1)	880-1¼ 781 (800-1¼)		NA
CIRCLING	880-1 777 (800-1)	920-1¼ 817 (900-1¼)		NA