



Federal Aviation Administration

SAFETY ALERT

Date: 12 April 2016
To: Users of the Coded Instrument Flight Procedures (CIFP)
From: Aeronautical Information Services (AIS)
Subject: Incorrect Navaid Coordinates for DLL, JST, VHP and HOC

Multiple NAVAID coordinate errors in the 28 APR, 2016 edition of the CIFP (1605):

The VOR latitude (5.36) for the CIFP record below is in error and should be as follows:

DLL (D) N43330300 vice N4333300

The VOR longitude (5.37) for the CIFP record below is in error and should be as follows:

JST (D) W078500300 vice W07850300

The VOR longitude (5.37) for the CIFP record below is in error and should be as follows:

VHP (D) W086220300 VICE W08622300

The NDB latitude (5.36) for the CIFP record below is in error for and should be as follows:

HOC (DB) N39110500 vice N3911500

These errors will be corrected in the CIFP for the 1606 cycle.