



# Federal Aviation Administration

---

---

## SAFETY ALERT

Date: May 20, 2021

To: Users of the Aeronautical Information Services 56 Day NASR Subscriber Files

From: Aeronautical Information Services, AJV-A

Subject: Airway **B4**

---

---

Effective 17 June 2021, The AWY.txt file of the 56 Day NASR Subscription, contains an error in B4. CURUP waypoint was inadvertently added between UTO and EAV. CURUP should be between EAV and FTO as shown below. This information will be updated in the 12 AUG 2021 AWY.txt subscriber file.

Designation	Point Seq	Nav Fac Fix Name(AWY2)	Nav Id (AWY2)	Nav Fac Fix Type (AWY2)	Nav Fac Fix State	Mea	Moca
B4	10	UTOPIA CREEK	UTO	NDB/DME	AK	8000	6200
B4	20	EVANSVILLE	EAV	NDB	AK	8000	6600
<b>B4</b>	<b>30</b>	<b>CURUP</b>		<b>WAY-PT</b>	<b>AK</b>	<b>8000</b>	<b>6600</b>
B4	40	YUKON RIVER	FTO	NDB	AK	8000	6600