



Federal Aviation Administration

SAFETY ALERT

Date: August 12, 2022

To: Users of the NASR 28 and 56 Day Subscriber Files

From: Aeronautical Information Services, AJV-A

Subject: OTM Front Course Bearing

Attention users of the NASR Subscriber Files. The ILS Front Course Bearing was not modified along with the Magnetic Variation update on 07/25/2022 in NFDD 141. This error was subsequently published in the ILS (.txt & .csv) subscriber file for effective date 09/8/2022. The correct OTM Front Course Bearing is 315.97. The OTM Front Course bearing of 315.97 will be in the 11/8/2022 ILS (.txt and .csv) subscriber files.