



Federal Aviation Administration

SAFETY ALERT

Date: October 3, 2014
To: Users of the Airport/Facility Directory (North Central Volume)
From: Aeronautical Navigation Products (AeroNav Products)
Subject: Incorrect Airport Diagram, Bismarck Muni, Bismarck ND (BIS)

The Airport/Facility Directory (A/FD) North Central Volume, effective 18 September, 2014, contains the incorrect Airport Diagram (AD) for Bismarck Muni, Bismarck ND (BIS). The correct AD can be found on the FAA AeroNav Products web site, at the following link:

<http://aeronav.faa.gov/d-tpp/1411/00051ad.pdf>