



## Federal Aviation Administration

---

---

# SAFETY ALERT

Date: 13 APR 2015  
To: Users of the Coded Instrument Flight Procedures (CIFP)  
From: Aeronautical Information Services (AIS)  
Subject: Incorrect HP leg length at KDKK\_R24

---

---

There are incorrect hold distances (5.27) in the 1505 edition of the CIFP.

The hold distances for fix identifier TRUNT in RNAV (GPS) Rwy 24 at Chautauqua Co/Dunkirk (KDKK\_R24) is incorrectly coded as 'T010' in two places. It should be correctly coded as '0040'.

These errors will be corrected in the CIFP for the 1506 cycle.