

FINAL COMMENT LOG

Originating Office: AFS-130	Document Title/Description: MMEL TBM-700 Rev 4, Daher Aerospace, TBM700, 850, 900, 910, 930, 940, 960, 980 (TBM700 A/B/C1/C2/N)	POC and Phone Number: Brett Hoben, brett.hoben@faa.gov	Suspense Date: 07/13/2026
--	--	---	--

Commenter Name and Organization	Date	Page #	Line, Para, or Item #	Comment	Recommendation	Response
John J McDermott AFS-220-3 Concur with comment	3/23/26	34-15 Pdf 68	34-43 Touchscreen Function	Repair category, NO Installed, number required for dispatch missing. Proviso is missing item title as per PL 31 # 13	Recommend either deleting item or combining item per PL 31 verbiage	Incorporated.
John J McDermott AFS-220-3 Concur with comment	3/23/26	77-1 Pdf 79	77-1 Engine Trend Condition and Monitoring System	Proviso refers to another MMEL item (28-3) without its title	Add 28-3 item title as per PL 31 #13	Incorporated.
AFS-300				No comments.		
AFS-400				No comments.		
AFS-800				No comments.		
Public Comment				No comments.		