



**FAA
Airports**

Errata Sheet for Advisory Circular (AC) 150/5230-4B, Aircraft Fuel Storage, Handling, Training, and Dispensing on Airports

Last Update: 4/6/2018

This errata sheet logs content errors and required updates identified after the Advisory Circular was signed on September 28, 2012. These errors have been corrected in the consolidated PDF version of the AC available on the FAA website.

#	Description of Correction	Location in Document	Rationale	Date Error Corrected
1	In the first sentence, replaced the word "supervisor" with "student".	Chapter 2, Par. 4b.	Wording change clarifies that all fueling personnel, not just the supervisor, must have hands-on training with a fire extinguisher every 2 years.	4/6/2018