

**Errata Sheet**  
for  
**Advisory Circular 150/5210-7D**  
**Aircraft Rescue and Fire Fighting Communications**

**Last Update: April 24, 2008**

This errata sheet logs content errors that were identified after the advisory circular (AC) was issued on 4/14/2008. These errors have been corrected in the electronic version of the AC available on the FAA website. All page numbers refer to the PDF version of the document posted on [www.faa.gov](http://www.faa.gov).

#	Description of Correction	Location	Rationale	Date Correction was Published
1	For "Flashing Red", replace the text in the "Aircraft on the Ground" column with the following: "Taxi clear of runway in use".	Page A-3, Appendix 2, Table A2, "Meaning of ATCT Light Gun Signals."	Corrects an error.	4/24/2008