

## Errata Sheet for

### Advisory Circular 150/5220-17B, Aircraft Rescue and Fire Fighting (ARFF) Training Facilities

Last Update: November 1, 2010

This errata sheet logs content errors that were identified after the advisory circular (AC) was published online on September 30, 2010. These errors have been corrected in the electronic version of the AC available on the FAA website.

All page numbers refer to the PDF version of the document posted on [www.faa.gov](http://www.faa.gov).

| # | Description of Correction   | Location | Rationale            | Date Error Corrected |
|---|---|----------|----------------------|----------------------|
| 1 | In paragraph 3.2.b(2)(b), change “with a diameter of least 115 feet (-1/+3 ft). A square or a rectangle, which will accommodate the required aircraft mockup, of an approximately equivalent area (12,273 ft <sup>2</sup> ) is acceptable”<br><br>to<br><br>“with a diameter of least <b>125</b> feet (-1/+3 ft). A square or a rectangle, which will accommodate the required aircraft mockup, of an approximately equivalent area ( <b>12,265</b> ft <sup>2</sup> ) is acceptable” [changes in bold]. | Page 12  | Typographical error. | 11/1/2010            |
|   |   |          |                      |                      |