

NOTICE

U.S. DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION

N 8900.127

National Policy

Effective Date:
07/02/10

Cancellation Date:
07/02/11

SUBJ: Cancellation of N 8900.111, Non-Relief Operations to Haiti


1. Purpose of This Notice. This notice cancels Notice N 8900.111, Non-Relief Operations to Haiti, dated February 12, 2010, which provided guidance for certificate-holding district offices (CHDO) and principal operations inspectors (POI) regarding resumption of non-relief flights to Port Au Prince, Haiti (MTPP) for Title 14 of the Code of Federal Regulations (14 CFR) parts 121, 135, and 125 (including part 125 Letter of Deviation Authority (LODA) holders, 125M), and issuance of operations specification (OpSpec)/letter of authorization (LOA) C567, Interim Authorizations, Provisions, and Limitations for Port Au Prince Airport (MTPP).

2. Audience. The primary audience for this notice is CHDO POIs with oversight responsibility of air carriers. The secondary audience includes Flight Standards (AFS) branches and divisions in the regions and in headquarters.

3. Where You Can Find This Notice. You can find this notice on the MyFAA Web site at https://employees.faa.gov/tools_resources/orders_notices/. Inspectors can access this notice through the Flight Standards Information Management System (FSIMS) at <http://fsims.avs.faa.gov>. Operators and the public may find this information at: <http://fsims.faa.gov>.

4. Guidance. AFS has determined that there is no longer a need for OpSpec/LOA C567, Interim Authorizations, Provisions, and Limitations for Port Au Prince Airport (MTPP). OpSpec/LOA C567 has been archived in the Web-based automated Operations Safety System (WebOPSS) and is no longer available for issuance. Normal operations have been resumed at Port Au Prince Airport. Operators no longer need the authorization of OpSpec/LOA C567 to operate to Port Au Prince Airport.

5. Disposition. We will not incorporate this notice into Order 8900.1, FSIMS. Direct questions regarding this notice to the Air Carrier Operations Branch, AFS-220, at (202) 267-8166.



for

John M. Allen
Director, Flight Standards Service