DOCUMENT CHANGE PROPOSAL/BRIEFING SHEET

FINAL DISPOSITION

ORDER/PUBLICATION: 7210.3W

CHANGE:

EFFECTIVE DATE: March 10, 2011 **TRACKING #: 32- 10-6-9**

2

SPECIALIST/ROUTING: Robert Law AJR-53 (202) 267-9326

1. <u>PARAGRAPH NUMBER AND TITLE</u>:

10-6-9. RUNWAY EDGE LIGHTS ASSOCIATED WITH MEDIUM APPROACH LIGHT SYSTEM/RUNWAY ALIGNMENT INDICATOR LIGHTS

2. <u>**BACKGROUND</u>:** The Three Step MALS/Three Step RAIL Intensity Settings, as depicted in TBL 10-6-1, do not comply with FAA Order 6850.2A, Visual Guidance Lighting Systems, Chapter 2, Paragraph 210, Table 2-3 Brightness Steps.</u>

3. <u>EXPLANATION OF CHANGE</u>: This change corrects the MALSR step intensity settings, to comply with guidance provided in FAA Order 6850.2A, Visual Guidance Lighting Systems, Chapter 2, Paragraph 210, TBL 2-3 Brightness Steps. This change cancels and incorporates N JO 7210.757, Runway Edge Lights Associated with Medium Approach Light System/Runway Alignment Indicator Lights, effective October 1, 2010.

4. <u>CHANGE</u>:

OLD

10-6-9. RUNWAY EDGE LIGHTS ASSOCIATED WITH MEDIUM APPROACH LIGHT SYSTEM/RUNWAY ALIGNMENT INDICATOR LIGHTS

			seeings		
Runway Edge Lights		Two Step MALS/One Step RAIL		Three Step MALS/Three Step RAIL	
Intensity		Intensity		Intensity	
HIRL	MIRL	MALS	RAIL	MALS	RAIL
Step 5	Step 3	100%	100%	100%	100%
Step 4			100%	100%	100%
Step 3	Step 2	10%	OFF	20%	26% outer 8% inner
Step 2			OFF	<u>OFF</u>	<u>4%</u>
Step 1	Step 1	OFF	OFF	4%	1%

TBL 10-6-1 MALSR Step Intensity Settings

10-6-9. RUNWAY EDGE LIGHTS ASSOCIATED WITH MEDIUM APPROACH LIGHT SYSTEM/RUNWAY ALIGNMENT INDICATOR LIGHTS

No change

NEW TBL 10-6-1 MALSR Step Intensity Settings

Runway Edge Lights		Two Step MALS/One Step RAIL		Three Step MALS/Three Step RAIL	
Intensity		Intensity		Intensity	
HIRL	MIRL	MALS	RAIL	MALS	RAIL
Step 5	Step 3	100%	100%	100%	100%
Step 4			100%	100%	100%
Step 3	Step 2	10%	OFF	20%	26% outer 8% inner
Step 2			OFF	<u>4%</u>	<u>1%</u>
Step 1	Step 1	OFF	OFF	4%	1%

No further changes to paragraph.

5. **INDEX CHANGES:** None

6. **<u>GRAPHICS</u>**: None

7. <u>GENOT/NOTICE</u>: N JO 7210.757, Runway Edge Lights Associated with Medium Approach Light System/Runway Alignment Indicator Lights, effective October 1, 2010

8. FORMATTING & PLAIN LANGUAGE REVIEW: X HM 2/23/2010

- 9. SAFETY RISK MANAGEMENT: (Check appropriate box).
 - SRMD. Proposed change meets full SMS requirements for safety risk assessment.
 - **SRMDM**. Proposed change is not safety related.
- 10. <u>ICAO DIFFERENCES</u>: YES D NO

1 Dodd

Manager, Terminal Operations Group

Date:

ICAO DIFFERENCES IDENTIFICATION FORM

PDG SME:

DATE:

ATO DCP #:

ICAO DIFFERENCE SARP/PANS

SPECIFIC US	PANS ATM, ANNEX	DESCRIPTION OF	REMARKS
REGULATION AND	PROVISION	DIFFERENCE	
REFERENCE			

DIFFERENCE CATEGORY:

DETERMINATION OF DIFFERENCE: YES D NO

VALIDATOR NAME: VALIDATOR PHONE: () -