

U.S. Department of Transportation Federal Aviation Administration

800 Independence Ave., SW. Washington, DC 20591

JUL 2 7 2016

Captain Mark Bradley Chairman Performance-based Operations Aviation Rulemaking Committee (PARC) Delta Airlines 1030 Delta Boulevard Atlanta, GA 30354-1989

Dear Captain Bradley:

I would like to thank the PARC for the recommendation to change Magnetic Variation (MV) tolerances for Very High Frequency Omnidirectional Range (VOR) related systems. We agree with the recommendation and are incorporating this change into Order 8260.19H and will be updating guidance in Advisory Circulars 90-100A and 90-105A.

The Federal Aviation Administration is also focusing on correcting existing VOR instrument flight procedures based on five degrees MV tolerance and updating these where necessary. Additionally, based on this change, we will encourage operators, equipment manufacturers, and database providers to review their own documents, databases, and/or tables to take action where appropriate.

If you have any questions, please contact Bruce DeCleene, Manager, Flight Technologies and Procedures Division, AFS-400, at (202) 267-8790.

Sincerely,

Margant gel

Margaret Gilligan Associate Administrator for Aviation Safety