

MAS G. TANCREDO
6TH DISTRICT, COLORADO

COMMITTEE ON RESOURCES

SUBCOMMITTEES:

WATER AND POWER

FORESTS AND FOREST HEALTH

COMMITTEE ON
INTERNATIONAL RELATIONS

SUBCOMMITTEES:

INTERNATIONAL TERRORISM,
NONPROLIFERATION AND HUMAN RIGHTS

AFRICA

ASIA AND THE PACIFIC

COMMITTEE ON THE BUDGET



Congress of the United States
House of Representatives
Washington, DC 20515-0606

June 23, 2005

WASHINGTON OFFICE:

1130 LONGWORTH HOUSE OFFICE BUILDING
WASHINGTON, DC 20515
MAIN: (202) 225-7882
FAX: (202) 226-4623

DISTRICT OFFICE:

6099 SOUTH QUEBEC STREET
SUITE 200
ENGLEWOOD, CO 80111-4547
MAIN: (720) 283-9772
FAX: (720) 283-9776

LITTLETON OFFICE:

1800 WEST LITTLETON BOULEVARD
LITTLETON, CO 80120-2021
MAIN: (720) 283-7575
SENIORS: (720) 283-9026

CASTLE ROCK OFFICE:

240 WILCOX STREET, SUITE 111
CASTLE ROCK, CO 80104-2439
MAIN: (303) 688-3361

Ms. Marion C. Blakey, Administrator
Federal Aviation Administration
800 Independence Avenue, SW
Room 1022
Washington, DC 20591

Dear Madam Administrator:

I am writing to ask for your immediate action in **grounding** Mitsubishi Heavy Industries' (MHI) MU-2B series aircraft. I feel this action is warranted due to the aircraft's abysmal flight safety record.

This matter was recently brought to my attention by my constituents, [REDACTED]. Their son and another pilot were killed while flying an MU-2B out of Centennial Airport near Denver on December 10, 2004. They apparently lost an engine shortly after takeoff and were unable to maintain aircraft control (the investigation is still pending).

To obtain some background on this particular aircraft, a member of my staff talked with Mr. Robert Cadwalader, an experienced MU-2B pilot and columnist for the *Atlantic Flyer* magazine. He stated that the aircraft is a 1950s design that employs a very small, straight wing in order to achieve impressive in-flight performance. However, because of this design feature, the aircraft needs very large flaps to allow for slower takeoff and landing speeds. This, in turn, necessitated the use of spoilers rather than the normal ailerons.

Unfortunately, in certain low altitude, low airspeed conditions deflecting a spoiler will increase drag at a time when additional lift is required. This situation is exacerbated if an engine is lost on takeoff, the landing gear is raised, the aircraft is at its maximum gross weight, and the airfield's elevation is above 5,000' MSL. Mr. Cadwalader also stated that post-accident reports that blame the pilot for "failing to maintain aircraft control" are far too simplistic—this aircraft can put a pilot in a position that is impossible to control! Because an entire wing can stall 'all at once', the MU-2B can go completely out of control in *less than one second* (at least two flipped upside down before the pilots could react).

In perusing the NTSB website, I noted that the MU-2 (known as the "Kill You 2" in pilot circles) has been involved in **187** accidents since 1962 (NTSB printout enclosed) —**238** people have died in 74 different fatal accidents. In addition to the Centennial crash, there were six other MU-2B accidents in 2004 (4 fatalities) and on May 24, 2005, another crash

www.house.gov/tancredo
tom.tancredo@mail.house.gov
CO School Safety Hotline:
(877) 542-SAFE

PRINTED ON RECYCLED PAPER


claimed four more lives in Oregon (the pilot had 17,000 flight hours!) I also noted that several MU-2B incidents involved propeller failures, while others involved what pilots described as a "loss of power" or "loss of torque." Therefore, it may very well be that there is a much more insidious problem inherent in this aircraft—something having to do with fuel or air flow disruption to engines. Of course, the statute of repose prohibits law suits against MHI unless it is revealed that the company knew about a high probability of mechanical/fuel failure.

Back in October, 1997, the FAA put forth an airworthiness directive (14 CFR Part 39 [62 FR 51594 NO. 191 10/02/97]; Docket No. 97-CE-94-AD; Amendment 39-10150; AD 97-20-14) stating that current training levels of pilots of the MU-2B made it difficult for them to recognize adverse operating conditions. While this AD related more specifically with flying in icing conditions, the same difficulty applies to loss of performance situations. The AD recommended additional pilot training. It should be noted that after the Centennial crash, MHI *became worried* that pilots were not being adequately trained to fly this aircraft. According to Ralph Sorrels, a deputy manager for MHI's product support division, the company is "deeply concerned" and recommends that MU-2 pilots get "specialized training in flight simulators so they can test emergency conditions and procedures in a safe environment."

Unfortunately, *I do not believe this action goes far enough. I am requesting that the aircraft be grounded* until a thorough review of **all** MU-2 accidents is made. Special emphasis should be paid to the relationship of engines problems to incidents/accidents. Additionally, it is my firm conviction that a special MU-2 series "type rating" be established. This pilot certification must be completed before any pilot is allowed to resume MU-2 flight operations.

Kindly send your reply to my Castle Rock district office. Thank you for your prompt attention to this letter—lives are at stake.

Very respectfully,



Tom Tancredo
Member of Congress

Enclosure

CC: Mr. Mark V. Rosenker, Acting Chairman, NTSB

**NTSB****National Transportation Safety Board**

490 L'Enfant Plaza, SW
Washington, DC 20594-0001
www.nts.gov

JUN 01 2005

Honorable Tom Tancredo
U.S. House of Representatives
240 Wilcox St.
Castle Rock, CO 80104

Attention: Terry Van Keuren

Dear Representative Tancredo:

We have received your request from our NTSB website regarding a list of all Mitsubishi MU-2 accidents in the United States since the aircraft was certified for use. Enclosed please find our list of accidents in the United States as well as abroad from 1968 through 2004. The list includes 187 MU-2 accidents, 177 of which we have issued a probable cause.

If you have any additional questions, please do not hesitate to contact me.

Sincerely,

A handwritten signature in black ink, appearing to read "Mark V. Rosenker", is written over a horizontal line.

Mark V. Rosenker
Acting Chairman

Enclosure

Mitsubishi MU-2 Accidents - 1968 to 2004

Date	NTSB Number	Location	Aircraft Type	Regist No.
03/09/68	NYC68F0411	PITTSBURGH, PA	MITSUBISHI MU-2B	N3560X
12/21/68	MKC69A0039	SPRINGFIELD, MO	MITSUBISHI MU-2B	N3550X
04/27/69	NYC69D0431	BRIDGEPORT, NJ	MITSUBISHI MU-2B	N3561X
01/05/70	NYC70AN067	TETERBORO, NJ	MITSUBISHI MU-2B	N11WF
01/16/70	IAD70AI039	SALISBURY, MD	MITSUBISHI MU-2B	N764Q
02/12/70	OAK70FVG02	SACRAMENTO, CALIF	MITSUBISHI MU-2B	N783Q
10/13/70	CHI71FGD22	NORTHFIELD, OHIO	MITSUBISHI MU-2B	N549LK
12/11/70	CHI71FBD44	OTTAWA, ILL	MITSUBISHI MU-2B	N322GB
04/28/71	FTW71FRA48	ALIEF, TEX	MITSUBISHI MU-2B	N780Q
10/15/71	FTW72FPG49	VAN BUREN, ARK	MITSUBISHI MU-2B	N3540X
11/24/71	CHI72DLQ23	BARDSTOWN, KY	MITSUBISHI MU-2F	N180MA
12/11/71	CHI72FEP24	EAST TROY, WIS	MITSUBISHI MU2B20	N304L
12/22/71	MKC72FCD49	LEMARS, IOWA	MITSUBISHI MU-2B	N251M
04/11/72	CHI72AC081	MILLERSBURG, OHIO	MITSUBISHI MU-2B	N8400E
04/16/72	NYC72AN129	ATLANTIC CITY, NJ	MITSUBISHI MU-2G	N132MA
08/15/72	CHI73FEI05	CLEVELAND, OHIO	MITSUBISHI MU-2B	N143MA
08/25/72	MIA73FKJ15	MONTGOMERY, ALA	MITSUBISHI MU-2B	N3543X
11/20/72	MIA73AM054	ALCOLU, SC	MITSUBISHI MU-2B	N757Q
01/12/73	CHI73FEA25	NOBLESVILLE, IND	MITSUBISHI MU-2B	N555C
01/31/73	CHI73AC067	DETROIT, MICH	MITSUBISHI MU-2	N866Q
06/13/73	FTW73DQG43	CEDILLOS C, MEX	MITSUBISHI MU-2B	N882Q
07/06/73	IAD74FKM03	N. WILKESBORO, NC	MITSUBISHI MU-2	N194MA
10/05/73	CHI74FEV22	SPRINGFIELD, ILL	MITSUBISHI MU-2	N887Q
12/03/73	FTW74AF040	COLEMAN, TEX	MITSUBISHI MU-2B	N307MA
01/11/74	CHI74AC059	ELYRIA, OHIO	MITSUBISHI MU-2B	N106MA
01/14/74	MIA74FKG49	COVINGTON, GA	MITSUBISHI MU-2K	N222HH
02/13/74	CHI74FEE51	ELGIN, ILL	MITSUBISHI MU2B	N261WR
03/02/74	DEN74AD041	GLENWOOD SPG, COLO	MITSUBISHI MU-2B	N711AH
10/14/74	MIA75AM022	SAVANNAH, GA	MITSUBISHI MU-2B	N222HH
12/02/74	ANC76FAA24	DEADHORSE, ALAS	MITSUBISHI MU-2J	N959L
09/14/75	NYC76DGM06	BEDFORD, PA	MITSUBISHI MU-2B	N492MA
11/13/75	IAD76AI033	JEFFERSON CITY, TN	MITSUBISHI MU-2K	N69QJ
12/26/75	HAY76AL042	ROLLINSVILLE, CO	MITSUBISHI MU-2B	N133MA
02/08/76	IAD76AI054	EASTON, MD	MITSUBISHI MU-2B	N300MA
02/18/76	NYC76AN080	ARGYLE, NY	MITSUBISHI MU2B20	N531MA
09/29/76	IAD76FLQ36	LOUISVILLE, KY	MITSUBISHI MU-2B	N122G
12/03/76	MIA77FKJ08	GADSDEN, AL	MITSUBISHI MU-2B	N304L
01/07/77	MKC77FA011	ROCHESTER, MN	MITSUBISHI MU-2B	N854Q
02/28/77	MIA77FKT24	PALM BEACH, FL	MITSUBISHI MU-2K	N282MA
03/18/77	FTW77FA045	AUSTIN, TX	MITSUBISHI MU-2B	N777MA
04/01/77	MIA77FA049	AUGUSTA, GA	MITSUBISHI MU-2B	N100SW
04/04/77	CHI77FEC25	YPSILANTI, MI	MITSUBISHI MU-2B	N321MA

04/05/77	NYC77FA046	BRONX,NY	MITSUBISHI MU-2	N888RJ
04/06/77	NYC77FNE14	BRIDGEPORT,CT	MITSUBISHI MU-2B	N234BC
04/24/77	OAK77DVA30	COALINGA,CA	MITSUBISHI MU-2B	N400KK
11/27/77	CHI78FEE10	ELGIN,IL	MITSUBISHI MU2B	N261WR
12/28/77	FTW78FPA10	ADDISON,TX	MITSUBISHI MU-2J	N245MA
01/17/78	IAD78FA034	CUMBERLAND,MD	MITSUBISHI MU2-J	N44KS
01/19/78	IAD78DLQ08	HAWESVILLE,KY	MITSUBISHI MU-2	N115S
02/12/78	UNKNOWN	NEIVA,COLUMBIA	MITSUBISHI MU2	N888MA
07/12/78	UNKNOWN	SAVNT LAKE,CANADA	MITSUBISHI MU-2	N19GU
08/25/78	DEN78FA065	RATON,NM	MITSUBISHI MU-2J	N178MA
08/28/78	NYC78FA085	BEDFORD,NH	MITSUBISHI MU-2P	N765MA
10/31/78	CHI79FEC02	YPSILANTI,MI	MITSUBISHI MU2B20	N13EW
01/23/79	FTW79FPG15	SEARCY,AR	MITSUBISHI MU-2B	N5NW
04/09/79	MKC79FCG38	GARDNER,KS	MITSUBISHI MU-2B	N251M
05/25/79	OAK79FVG43	SACRAMENTO,CA	MITSUBISHI MU2	N312MA
06/18/79	FTW79DA088	NEW ORLEANS,LA	MITSUBISHI MU-2B	N222LR
08/03/79	MKC79FA046	HAYS,KS	MITSUBISHI MU-2B	N208MA
10/17/79	CHI80DEG01	PIQUA,OH	MITSUBISHI MU-2B	N855Q
11/01/79	IAD80FA007	NASHVILLE,TN	MITSUBISHI MU-2F	N873Q
11/26/79	FTW80FA019	POST OAK,TX	MITSUBISHI MU-2B	N234MA
12/21/79	DEN80FA012	PROVO,UT	MITSUBISHI MU-2B	N200BR
02/14/80	FTW80FA042	HOUSTON,TX	MITSUBISHI MU-2B	N346MA
02/23/80	FTW80FA048	NEW ORLEANS,LA	MITSUBISHI MU-2B	N962MA
03/21/80	CHI80FEG10	CINCINATI,OH	MITSUBISHI MU2B60	N258MA
04/23/80	LAX81FA088	HENDERSON,NV	MITSUBISHI MU-2B	N307MA
11/01/80	FTW81FQA08	ROSWELL,NM	MITSUBISHI MW-2B	N10FR
11/02/80	DEN81DTM03	PROVO,UT	MITSUBISHI MU2-35	N18WP
11/30/80	FTW81FRG08	PORT ARANSAS,TX	MITSUBISHI MU-2J	N44MR
12/06/80	CHI81FA010	RAMSEY,MN	MITSUBISHI MU-2	N969MA
12/15/80	CHI81FEG03	CAMBELLSTOWN,OH	MITSUBISHI MU-2B	N93UM
01/11/81	FTW81FQA13	ALBUQUERQUE,NM	MITSUBISHI MU-2B	N306H
01/21/81	CHI81FET04	WABASH,IN	MITSUBISHI MU-2B	N770MA
04/19/81	FTW81FA075	LAJITAS,TX	MITSUBISHI MU-2B	N500GL
04/23/81	CHI81FA051	ALPENA,MI	MITSUBISHI MU-2B	N9JS
05/13/81	MIA81FA072	MIAMI,FL	MITSUBISHI MU-2	N92JR
05/21/81	MIA81FLD44	LAKELAND,FL	MITSUBISHI MU-2B	N741MA
09/02/81	FTW81FA139	MCLEOD,TX	MITSUBISHI MU-2B	N233MA
09/06/81	DEN81AA064	RIVERTON,WY	MITSUBISHI MU-2B	N3ED
09/13/81	LAX81DUQ33	GOLETA,CA	MITSUBISHI MU-2	N100NP
09/24/81	DEN81FA067	FLAGSTAFF,AZ	MITSUBISHI MU-2B	N16CG
11/05/81	DEN82FA006	SARATOGA,WY	MITSUBISHI MU-2B	N53AD
11/18/81	DEN82FA008	EAGLE,CO	MITSUBISHI MU-2B	N444AR
11/19/81	MIA82FA112	JACKSONVILLE,FL	MITSUBISHI MU-2B	N750MA
11/22/81	LAX82DA017	PAGO PAGO,A SAMOA	NITSUBISHI MU-2B	N109TW
12/04/81	SEA82DYM06	MADRAS,OR	MITSUBISHI MU-2B	N442MA
12/08/81	DEN82FTG02	WILLISTON,ND	MITSUBISHI MU-2B	N40AM

02/03/82	DEN82DA029	HAYDEN, CO	MITSUBISHI MU2B-40	N149JA
04/20/82	ATL82FA110	LAFAYETTE, GA	MITSUBISHI MU-2B-30	N165MA
07/13/82	LAX82FA255	SCHELLVILLE, CA	MITSUBISHI MU-2B	N27GP
08/18/82	MKC82DA146	CAMDENTON, MO	MITSUBISHI MU-2B-20	N550MA
09/12/82	DEN82AA191	HAYDEN, CO	MITSUBISHI MU-2B-25	N66U
11/11/82	DEN83LA017	ENGLEWOOD, CO	MITSUBISHI MU-2B-60	N274MA
12/14/82	ATL83LA064	COLUMBIA, SC	MITSUBISHI MU-2	N522MA
12/15/82	ATL83FA063	LOUISVILLE, KY	MITSUBISHI MU-2B	N5589S
12/15/82	CHI83LA051	MUSKEGON, MI	MITSUBISHI MU-2B-20	N45EV
01/20/83	FTW83LA096	LUBBOCK, TX	MITSUBISHI MU-2B-30	N555CH
01/27/83	LAX83FA083	SCOTTSDALE, AZ	MITSUBISHI MU-2B-60	N440MA
03/18/83	DEN83FTE08	FORT COLLINS, CO	MITSUBISHI MU-2B-40	N181RS
03/18/83	NYC83FA078	NORTH ADAMS, MA	MITSUBISHI MU-2B-60	N473MA
03/24/83	DCA83AA022	JEFFERSONVILLE, GA	MITSUBISHI MU-2B-60	N72B
04/14/83	NYC83LA096	WEST MIFFLIN, PA	MITSUBISHI MU-2B-26	N79AC
10/20/83	FTW84FA028	PATTERSON, LA	MITSUBISHI MU-2B	N444PA
11/04/83	DEN84LA050	RICHFIELD, UT	MITSUBISHI MU-2B-60	N477MA
01/24/84	MKC84LA064	AMES, IA	MITSUBISHI MU 2B-20	N123AX
03/23/84	ATL84LA132	CHARLOTTE, NC	MITSUBISHI MU-2B-20	N5HE
04/19/84	DCA84AA022	BURLINGTON, CT	Mitsubishi MU-2B-60	N466MA
06/09/84	FTW84LA267	SUGARLAND, TX	MITSUBISHI MU-2N	N850MA
12/01/84	FTW85LA067	ROBERT LEE, TX	MITSUBISHI MU-2B-35	N112SK
01/04/85	BFO85FA011	WEST POINT, VA	MITSUBISHI MU-2B-25	N275MA
04/14/85	FTW85LA183	PATTERSON, LA	MITSUBISHI MU2J	N808W
05/21/85	FTW85LA229	SAN ANGELO, TX	MITSUBISHI MU-2B-20	N711LL
07/11/85	NYC85FA163	SOUTHBRIDGE, MA	MITSUBISHI MU-2B-26	N727MA
10/16/85	FTW86FA015	EL PASO, TX	MITSUBISHI MU-2B-2D	N23CD
03/05/86	CHI86FA098	EOLA, IL	MITSUBISHI MU-2B-60	N513DC
06/02/86	FTW86MA097	BARTLETT, TX	MITSUBISHI MU-2B-35	N8CC
10/12/86	DEN87FA003	DENVER, CO	MITSUBISHI MU-2B-20	N3MU
06/18/87	ATL87FA173	CORAL SPRINGS, FL	MITSUBISHI MU-2B	N184MA
07/02/87	MKC87FA130	KANSAS CITY, MO	MITSUBISHI MU-2B-60	N271MA
07/16/87	ATL87LA219	WINCHESTER, TN	MITSUBISHI MU-2B-36A	N702H
12/07/87	NYC88LA055	WHITE PLAINS, NY	MITSUBISHI MU-2B-20	N866Q
12/23/87	MIA88WA074	SAN SALVADOR,	MITSUBISHI MU-2B-30	N255C
02/12/88	NYC88LA085	PHILADELPHIA, PA	MITSUBISHI MU-2B-35	N339MA
11/16/88	CHI89FA026	CHICAGO, IL	MITSUBISHI MU-2B-60	N271MA
12/09/88	DCA89LA012	MISSING, PO	MITSUBISHI MU-2J	N296MA
01/02/89	ATL89FA065	MANSFIELD, OH	MITSUBISHI MU-2B	N500V
02/17/89	SEA89LA061	SPOKANE, WA	MITSUBISHI MU-2B-35J	N54US
02/28/89	BFO89LA023	SAN DIEGO, CA	MITSUBISHI MU-2B-20F	N701DM
03/31/89	NYC89FA111A	SYRACUSE, NY	MITSUBISHI MU-2B-35	N638MA
01/09/90	MIA90LA051	JACKSONVILLE, FL	MITSUBISHI MU-2B-25	N666HB
01/19/90	DEN90LA047	BROOMFIELD, CO	MITSUBISHI MU-2B-25	N99SR
01/23/90	ATL90LA053	NASHVILLE, TN	MITSUBISHI MU2B-20	N40RP
02/09/90	DEN90FA055	RAPID CITY, SD	MITSUBISHI MU-2B-60	N64MD

02/09/90	NYC90LA066A	TETERBORO, NJ	MITSUBISHI MU-2B-35	N349MA
02/09/90	NYC90LA066B	TETERBORO, NJ	MITSUBISHI MU-2B-35	N533DM
02/14/90	FTW90FA072	PUTNAM, TX	MITSUBISHI MU-2B-60	N300CW
09/06/90	ATL90FA163	NASHVILLE, TN	MITSUBISHI MU-2B-36	N82MA
02/22/91	FTW91FA043	TULSA, OK	MITSUBISHI MU-2B-60	N274MA
05/07/91	FTW91FA074A	KENEFIC, OK	MITSUBISHI MU-2B-20	N106MA
06/28/91	LAX91FA280	GOLETA, CA	MITSUBISHI MU-2B-36A	N2CJ
09/27/91	NYC91LA250	UTICA, NY	MITSUBISHI MU-2B-60	CFFSS
03/05/92	DEN92FA040	NEW CASTLE, CO	MITSUBISHI MU-2B-60	N303CA
05/18/92	LAX92TL#06	EDWARDS AFB, CA	MITSUBISHI MU2B-36	N742FN
06/24/92	DEN92FA064	ALAMAGORDO, NM	MITSUBISHI MU-2B-30	N108SC
07/09/92	BFO92FA094	CONCORD, NH	MITSUBISHI MU-2B-40	N220MA
08/18/92	NYC92LA166	PHILADELPHIA, PA	MITSUBISHI MU-2-60	N66LA
09/11/92	DCA92MA049A	GREENWOOD, IN	MITSUBISHI MU-2B-60	N74FB
11/20/92	DEN93LA013	BROOMFIELD, CO	MITSUBISHI MU-2B-25	N473FW
01/05/93	ANC93LA025	NOME, AK	MITSUBISHI MU-2B-35	N900YH
04/06/93	SEA93FA088	CASPER, WY	MITSUBISHI MU-2B-35	N96JP
04/19/93	DCA93GA042	ZWINGLE, IA	MITSUBISHI MU-2B-60	N86SD
08/29/93	NYC93FA177	S. CHARLESTON, WV	MITSUBISHI MU-2B-40	N965MA
09/21/95	MIA95FA226	SMYRNA, TN	MITSUBISHI MU-2B-35	N309MA
01/15/96	SEA96MA043	MALAD CITY, ID	Mitsubishi MU-2B-36	N693PA
01/18/96	NYC96LA053	ALLENTOWN, PA	Mitsubishi MU-2B-6	N888TP
01/19/96	MIA96FA067	WEST COLUMBIA, SC	Mitsubishi MU-2B-60	N50KW
04/07/96	ATL96LA078	BATESVILLE, MS	Mitsubishi MU-2B	N310MA
05/16/96	FTW96LA215	HOUSTON, TX	Mitsubishi MU-2B-40	N40AM
07/20/96	LAX96LA280	SCOTTSDALE, AZ	Mitsubishi MU-2B	N999FA
09/28/96	NYC96LA188	CHILLICOTHE, OH	Mitsubishi MU-2B-30	N618BB
12/30/97	CHI98FA074	WAYNE, IL	Mitsubishi MU-2B-30	N999WB
08/08/98	MIA98LA223	MIAMI, FL	Mitsubishi MU-2	N110GC
11/04/98	CHI99FA023	ROCK, KS	Mitsubishi MU-2B-60	N5LN
03/12/99	ATL99LA054	KNOXVILLE, TN	Mitsubishi MU-2B-20	N176BJ
05/24/99	NYC99WA121	PERRY SOUND,	Mitsubishi MU-2B-40	N701K
01/22/00	FTW00FA070	San Antonio, TX	Mitsubishi MU-2B-26A	N386TM
02/11/00	CHI00FA070	LEWISTON, ID	Mitsubishi MU-2B-60	N152BK
08/24/00	FTW00LA242	CORSICANA, TX	Mitsubishi MU-2B-35	N770MA
10/06/00	NYC01FA005	Edgartown, MA	Mitsubishi MU-2B-26A	N60BT
12/21/00	DEN01LA032	ASPEN, CO	Mitsubishi MU-2B-60	N130MS
05/01/01	FTW01FA111	The Woodlands, TX	Mitsubishi MU-2B-40	N16CG
06/10/01	DEN01FA113	Cerrillos, NM	Mitsubishi MU-2B-20	N187AF
08/01/01	MIA01FA206	Hilton Head, SC	Mitsubishi MU-2B-35	N1VY
11/30/01	CHI02LA044	St Paul, MN	Mitsubishi MU-2B-40	N9052Y
04/15/02	MIA02FA084	Carolina, PR	Mitsubishi MU-2B-35	N45BS
05/28/02	CHI02LA144	Belleville, MI	Mitsubishi MU2B-20	N54CK
01/28/03	NYC03LA046	Cleveland, OH	Mitsubishi MU-2B-60	N941MA
04/18/03	DEN03LA075	Salt Lake City, UT	Mitsubishi MU-2B-60	N157CA
11/02/03	MIA04WA027	Bonaire,	Mitsubishi MU-2B-35	N630HA

03/11/04	LAX04FA165	Napa, CA	Mitsubishi MU-2B-40	N966MA
03/25/04	NYC04FA093	Pittsfield, MA	Mitsubishi MU-2B-36	N201UV
03/27/04	LAX04LA174	La Verne, CA	Mitsubishi MU-2B-26A	N81MF
05/14/04	IAD04FA021	Ferndale, MD	Mitsubishi MU-2B-60	N755AF
06/15/04	CHI04LA155	Waukegan, IL	Mitsubishi MU-2B-40	N77DK
11/30/04	NYC05LA025	Philadelphia, PA	Mitsubishi MU-2	N941MA
12/10/04	DEN05FA034	Englewood, CO	Mitsubishi MU-2B-60	N538EA