

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: SID	Estimated Chart Date: 09/03/2026	APWS Task ID: 4757C275B379493EA46DED6B5C386583	APWS Project ID: 444E97F1549F4566B6F90194D4E78ADA
Procedure: CINDER ONE DEPARTURE		Enroute: YES	Specialist: Tuttle, Judith		Agreement Number:
Airport ID: KBDN			Airport City: BEND		State: OR
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: ACTIVE AIRPORT DATA USED. ORIGINAL PROCEDURE. CONTACT: RAKE MCGRAW (AJV-A422), 405.954.8711. QUALITY 41 CHECKED QUALITY 23 CHECKED					

FIPC BASIC FORM								
PROCEDURE: CINDER ONE DEPARTURE			AIRPORT NAME: BEND MUNI		AIRPORT ID: KBDN	SPECIAL CONTROL NO: SP-04-187-26		
FAC ID: KBDN		CITY: BEND			ST: OR	ORIG CHART DATE: 09/03/2026		
DFL TYPE: PROC/T	THIRD PARTY: ☐ YES	EST. TIME ON SITE: 0.4	REIMB. NUMBER:		PTS TASK ID: 4757C275B379493EA46DED6B5C386583			
PREFLIGHT NOTES								
REVIEWER: jordan rolih					DATE: 05/07/2026			
COMMENTS:					CHECK ONE: ☒ FLT CK REQ ☐ NFCR ☐ REJECT			
							YES	NO
					CPV COMPLETE?		X	
PROCEDURE RESULTS								
INSPECTION DATE: 05/06/2026		CREW #: VN408	N #: N76	INSTRUMENT PROCEDURE STATUS: ☒ SAT ☐ SAT W/CHANGES ☐ UNSAT		ARINC CODING: ☒ SAT ☐ SAT/GOLD ☐ UNSAT		
FLIGHT INSPECTOR SIGNATURE: jordan rolih @ 05/07/2026 08:39			PRINTED NAME: ROLIH, JORDAN ALEXANDER			NOTAM INITIATED? ☐ YES ☒ NO		
FLIGHT INSPECTOR REMARKS:								
IN-FLIGHT OBSTACLE REPORT								
OBSTRUCTION ID #:	COORDINATES OR LOCATION:		GNSS ALTITUDE (MSL):		BAROMETRIC ALTITUDE (MSL):		HEIGHT ABOVE GROUND LEVEL:	