

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: Textual DP	Estimated Chart Date: 08/07/2025	APWS Task ID: 5DBFC3CE066A4A058110307E7068E1D1	APWS Project ID: 3D7A04DDF29A4C5EA180BB87403300A2
Procedure: TAKEOFF MINIMUMS AND OBSTACLE DP ORIG		Enroute: YES	Specialist: Keefer, John		Agreement Number:
Airport ID: 3W7			Airport City: ELECTRIC CITY		State: WA
Facility ID:	Facility Type:	Flight Inspection Remark Type: Hold FC Slot			
Procedure Comments: VFR TO IFR DOCKET 22-ANM-84 CONTACT CASIMIR TABAKA 405-954-7931 2/25/25: THIS IS AN UPDATED COPY OF THE FORM DEVELOPED ON 2/21/23. 1. UPDATED TAKEOFF OBSTACLES. 2. CHANGED DOCKET NUMBER FROM 22-AMN-84 TO 22-ANM-84 ON COVERSHEET. 7/16/25: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 3/10/25. MOVED RWY 22: USE SINGG DEPARTURE FROM TAKEOFF MINIMUMS TO TEXTUAL DEPARTURE PROCEDURES. QUALITY 26 CHECKED QUALITY 16 CHECKED					

FIPC BASIC FORM						
PROCEDURE: TAKEOFF MINIMUMS AND OBSTACLE DP ORIG			AIRPORT NAME: GRAND COULEE DAM		AIRPORT ID: K3W7	SPECIAL CONTROL NO: SP-07-175-24
FAC ID: K3W7		CITY: ELECTRIC CITY			ST: WA	ORIG CHART DATE: 02/20/2025
DFL TYPE: PROC/T	THIRD PARTY: ☐ YES	EST. TIME ON SITE: 0.4	REIMB. NUMBER:	PTS TASK ID: 5DBFC3CE066A4A058110307E7068E1D1		
PREFLIGHT NOTES						
REVIEWER: jordan rolih					DATE: 02/13/2025	
COMMENTS:					CHECK ONE: ☒ FLT CK REQ ☐ NFCR ☐ REJECT	
					 YES NO	
					CPV COMPLETE? X 	
PROCEDURE RESULTS						
INSPECTION DATE: 02/12/2025	CREW #: VN408	N #: N90	INSTRUMENT PROCEDURE STATUS: ☐ SAT ☒ SAT W/CHANGES ☐ UNSAT		ARINC CODING: ☐ SAT ☐ SAT/GOLD ☐ UNSAT	
FLIGHT INSPECTOR SIGNATURE: jordan rolih @ 02/13/2025 10:30			PRINTED NAME: ROLIH, JORDAN ALEXANDER			NOTAM INITIATED? ☐ YES ☒ NO
FLIGHT INSPECTOR REMARKS: Climb gradient works but, curent departure instructions say "climb on heading 216 to 2300, the climbing right turn direct to cross SINGG at or above the MEA/MCA for route of flight." Suggest changing the initial heading after departure to 200 to 2300 feet, instead of 216. This ensures terrain is cleared if the climb gradient is not maintained.						
IN-FLIGHT OBSTACLE REPORT						
OBSTRUCTION ID #:	COORDINATES OR LOCATION:	GNSS ALTITUDE (MSL):	BAROMETRIC ALTITUDE (MSL):	HEIGHT ABOVE GROUND LEVEL:		