

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 05/16/2024	APWS Task ID: 623EDAA944B444ECA296F234B3690046	APWS Project ID: A100817577004611858546248C3A5E0B
Procedure: RNAV (GPS) RWY 22 AMDT 1A		Enroute: NO	Specialist: Boone-walt, Rose		Agreement Number:
Airport ID: KMZZ			Airport City: MARION		State: IN
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: Clears NTM FDC 1/9095 CONTACT: DAVID M. DANNER AJV-A421 LEAD: 405.954.5077 QUALITY 41 CHECKED QUALITY 32 CHECKED Digitally signed by PABLO ORTIZ-JR Feb 21, 2024					

FIPC BASIC FORM								
PROCEDURE: RNAV (GPS) RWY 22 AMDT 1A		AIRPORT NAME: MARION MUNI - MCKINNEY FLD		AIRPORT ID: KMZZ	SPECIAL CONTROL NO: BG-02-293-24			
FAC ID: KMZZ22.01		CITY: MARION			ST: IN	ORIG CHART DATE: 06/13/2024		
DFL TYPE: PROC/G	THIRD PARTY: ☐ YES	EST. TIME ON SITE: 0.5	REIMB. NUMBER:	PTS TASK ID: 623EDAA944B444ECA296F234B3690046				
PREFLIGHT NOTES								
REVIEWER:					DATE:			
COMMENTS:					CHECK ONE: ☐ FLT CK REQ ☐ NFCR ☐ REJECT			
							YES	NO
					CPV COMPLETE?			
PROCEDURE RESULTS								
INSPECTION DATE: 03/13/2024	CREW #: VN357	N #: N77	INSTRUMENT PROCEDURE STATUS: ☒ SAT ☐ SAT W/CHANGES ☐ UNSAT		ARINC CODING: ☒ SAT ☐ SAT/GOLD ☐ UNSAT			
FLIGHT INSPECTOR SIGNATURE: james onieal @ 03/13/2024 22:41			PRINTED NAME: ONIEAL, JAMES BRIAN			NOTAM INITIATED? ☐ YES ☒ NO		
FLIGHT INSPECTOR REMARKS:								
IN-FLIGHT OBSTACLE REPORT								
OBSTRUCTION ID #:	COORDINATES OR LOCATION:	GNSS ALTITUDE (MSL):	BAROMETRIC ALTITUDE (MSL):		HEIGHT ABOVE GROUND LEVEL:			

RNAV (GPS) RWY 22

MARION MUNI - MCKINNEY FLD (MZZ)

T Rwy 22 helicopter visibility reduction below $\frac{3}{4}$ SM NA.

MISSED APPROACH: Climb to 2700 direct AKICA and hold.

Procedure NA for arrivals at
FORCE on V96 northeast bound.

(IAF) FORCE
2500 NoPT
149°
(8.1)

4 NM
041°
221°
HOLD 6000
2500

(IF/IAF) BALAC

2500 NoPT
293°
(11)

(IAF) AJAYS

ERUCT
1.8 NM to
RW22

(FAF) DUSEY

2500
221°
(6)

980 A 997

RW22 981 A

A 1107

Procedure NA for arrivals at
AJAYS on V221 southbound.

MSA RW22 25 NM
2900

A compass rose with a star-like center. A line points to the 040° mark on the outer ring. Another line points to the 220° mark. A third line points to the 41 mark on the inner ring.

MZZ
MARION MUNI-MCKINNEY FLD
MARION, IN
CIRCLING
1:100K

